





NOTE: STANDOFF BRACKET LOCATIONS

ARE ± 1".

DO NOT PREDRILL HOLES IN THE STRUCTURE. HOLES SHOULD BE MATCH DRILLED TO INSURE PROPER ALIGNMENT



